

Client and Site address <i>Basildon Hospital</i> <i>Nether Mayne</i> <i>Basildon</i> <i>SS16 5NL</i> Site Location <i>Burleshouse</i>	Invoice Address (if different)	Inv. No.	
		Our Ref.	<i>23696</i>
		Order No.	
		Contact	

Description of Works <i>Softener leaking</i>
Comments <i>On Arrival n° 2 leaking from rear of brine Valve.</i> <i>Isolated unit &amp; investigated found Nut split as well as brine Valve.</i> <i>Supplied &amp; fitted new brine Valve with Nut</i> <i>Tested out :- All ok</i> <i>Returned to operation</i>

Quantity	Description	Quantity	Description	Any Further Action (Delete as applicable)	
<i>1</i>	<i>1710 40PM brine Valve.</i>			Yes	No
	<i>Wbs + Screws</i>			Parking	C/Charge
					<i>Toll. DC</i>

I acknowledge the above work has been carried out to my satisfaction and that the Plant has been left in accordance with my instruction.	Customer Signature <i>[Signature]</i>	Print Name <i>SANAL</i>	Start Date <i>25/2/25</i>
	Engineer Signature <i>[Signature]</i>	Print Name <i>Dave</i>	End Date <i>25/2/25</i>
Travel Hours <i>2 1/2</i>	Mileage <i>100 +</i>	Time Started on Site: <i>07.00</i>	Time Finished on Site: <i>10.00</i>
		Total Hours	